

## TEMPORARY REVISION

### OM-TR-MDC-E4-334a

### EECU Software VC33\_x\_05\_17

This Temporary Revision OM-TR-MDC-E4-334a is approved in conjunction with the Mandatory Design Change Advisory MDC-E4-334a and is valid in conjunction with the latest revision of the Operation Manual (OM) until this Temporary Revision has been incorporated into the OM.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the OM.

The technical information contained in this document has been approved under the authority of DOA ref. EASA.21J.0399.

Doc. Nr.	Affected Section(S)	Affected Page(s)s
E4.01.01	7	16a 20a

#### **Instruction:**

- Print this document on yellow paper (single-sided)
- Insert this cover page as the first page of the OM
- Insert the other pages of this Temporary Revision adjacent to or in front of the corresponding OM pages

*Following section is amended to read:*

### **7.6.3.3 Caution Handling Table Software VC33\_x\_05\_17**

The table in this section applies to SW version VC33\_x\_05\_17 and later versions.

*The existing table is amended to read:*

Failure description	Failure Code	Caution Indication	Caution Latched	ECU Switch Over
Watchdog communication failure	2321	NO	NO	YES



*Following section is removed:*

~~7.6.3.4 ——— Caution Handling Table Software VC33\_x\_05\_13~~